

PERCH LAKE TOWNSHIP ROAD INSPECTION TOUR
Conducted April 27,2021

| Road | Miles | Section/ Road # | Paved/ Unpaved | Description of Work Needed or Road Conditions |
|---------------------|-------|--------------------|-------------------|---|
| Bayview Drive | 0.05 | 21 T | P | Did not inspect |
| Bergman Road | 0.80 | 12 NW T 311 | | Brushing completed fall 2020 |
| Bob's Drive | 0.20 | 21 T | P | Replace culvert #34 |
| Brower Drive | 0.30 | 21 T 399 | P | Patch blacktop where culverts were replaced in 2021 |
| Cedar Lake | 0.50 | 10/15 T 528 | | Low spot each side of culvert needs class 5. |
| Ditchbank Road | 2.50 | 17/20 T 421 | | Road very rough due to pipeline activity. Needs Class 5 on top of rock that pipeline contractor put on road. Sent proposal to Enbridge for repairs from Mission Rd to First Bridge. Class 5 also needed south of second bridge. |
| Enger Road | 0.30 | 15/16 T 191 | | No Change |
| Hardwood Lake Road | 0.75 | 3/10 T 159 | P | Dust control needed on ground pavement, west 900 feet |
| Homestead Road | 0.70 | 21/28 T 248 | P | No Change Do we want to stripe this one? |
| Jarvinen Road | 0.60 | 27 T 138 | P | Road shouldering near culvert |
| Kotiranta Road | 0.33 | 23 T 303 | | LOOKS GOOD |
| Lake Road | 0.50 | 28 SW T 523 | P | |
| Lakeview Drive | 1.10 | 28 T 524 | P | Pothole south of Watkins spur. Subsidence near 1040 Lakeview needs fill, Rock? |
| Lyndhurst Bay Drive | 1.00 | 21 T 400 | P | Trees close to road 3-4 should be removed. Pothole 925 needs filling. Alligator cracking south of 904 Lyndhurst Bay. |
| Magney Drive | 1.40 | 21 T | P | Pothole Bob's drive and south. Crumbling blacktop west of Cary Road. |

PERCH LAKE TOWNSHIP ROAD INSPECTION TOUR
Conducted April 27,2021

| Road | Miles | Section/ Road # | Paved/ Unpaved | Description of Work Needed or Road Conditions |
|------------------------|-------|--------------------|-------------------|--|
| Maple Drive | 1.10 | 33 T 439 | P | Pothole just east of County 7. Alligator cracking East 50 ft. Should be part of County 7 Project |
| Pine Grove Drive | 0.40 | 33 NE T 522 | P | Stripping 2021. A fair bit of alligator cracking next candidate for grind and re-pave |
| Reponen Road | 3.60 | 25 T 329 | | Class V from Strand to Moorhead Rd. Monitor beaver activity south of Connor's Road |
| Salmi Road | 0.85 | 22/33 T 304 | P | Needs fill on the shoulders both sides for most of the road. |
| Simian Creek Drive | 0.30 | 2/11 T 160 | | No change |
| Strand Road | 2.10 | 27/34 T 132 | | Add class 5 near Enbridge crossing |
| Town Road 535 | 1.50 | 7 T 535 | | No Change |
| Town Road 536 | 1.00 | 7/18 T 536 | | No change |
| Watkins Spur | 0.35 | 28 NW T 525 | P | Add Class 5 as needed. finish engineering for grind and repave. We need to fill the holes with class 5 soon. |
| | | | | |
| TOTAL MILES | 22.23 | | | |

Supervisors Present

Keith Depre

Gary Harms

Steve Olson