

PERCH LAKE TOWNSHIP ROAD INSPECTION TOUR
Conducted April 20, 2019

Road	Miles	Section/ Road #	Paved/ Unpaved	Description of Work Needed or Road Conditions
Bayview Drive	0.05	21 T	P	No Change
Bergman Road	0.80	12 NW T 311		Add Class 5
Bob's Drive	0.20	21 T	P	No Change
Brower Drive	0.20	21 T 399	P	Culvert Replacement
Cedar Lake	0.50	10/15 T 528		No Change
Ditchbank Road	2.50	17/20 T 421		Need to further inspect cross culvert south of second bridge
Enger Road	0.30	15/16 T 191		No Change
Hardwood Lake Road	0.75	3/10 T 159	P	Crack patch to 3012 Class 5 gravel from 3012 to end of pavement.
Homestead Road	0.70	21/28 T 248	P	Crack Patch
Jarvinen Road	0.60	27 T 138	P	Did not inspect
Kotiranta Road	0.33	23 T 303		Culvert #20 needs replacing
Lake Road	0.50	28 SW T 523	P	Striping
Lakeview Drive	1.10	28 T 524	P	Replace driveway entrance culvert at 964 and #46? & 44? cross culvert(s). Cross culverts when Watkins spur is reconstructed.
Lyndhurst Bay Drive	1.00	21 T 400	P	Crack Patch
Magney Drive	1.40	21 T	P	Crack Patch
Maple Drive	1.10	33 T 439	P	Striping

PERCH LAKE TOWNSHIP ROAD INSPECTION TOUR
Conducted April 20, 2019

Road	Miles	Section/ Road #	Paved/ Unpaved	Description of Work Needed or Road Conditions
Pine Grove Drive	0.40	33 NE T 522	P	Striping
Reponen Road	3.60	25 T 329		Add class 5 east of 1022
Salmi Road	0.85	22/33 T 304	P	Striping
Simian Creek Drive	0.30	2/11 T 160		No change
Strand Road	2.10	27/34 T 132		Add class 5 especially in wetland crossings
Town Road 535	1.50	7 T 535		No Change
Town Road 536	1.00	7/18 T 536		No change
Watkins Spur	0.35	28 NW T 525	P	Add Class 5 as needed
Wilshire Drive	0.10	T 21	P	Did not inspect
TOTAL MILES	22.23			
Supervisors Present				
<hr/> Keith Depre				
<hr/> Gary Harms				
<hr/> Steve Olson				