

Perch Lake Township  
Road Inspection Tour April 25, 2022

Road	Miles	Section/ Road #	Paved/ Unpaved	Description of Work Needed or Road Conditions
Bayview Drive	0.05	21 T	P	Crack patch
Bergman Road	0.80	12 NW T 311		No needs observed
Bob's Drive	0.20	21 T	P	Replace culvert #34
Brower Drive	0.20	21 T 399	P	Crack patch
Cedar Lake	0.50	10/15 T 528		Add Class V
Ditchbank Road	2.50	17/20 T 421		Ditchbank Road is in much better condition than last year. Need signage for first bridge.
Enger Road	0.30	15/16 T 191		Add Class V
Hardwood Lake Road	0.75	3/10 T 159	P	Need class V at end of blacktop
Homestead Road	0.70	21/28 T 248	P	No Change
Jarvinen Road	0.60	27 T 138	P	Road shouldering near culvert. Need dead-end sign.
Kotiranta Road	0.33	23 T 303		Looks good
Lake Road	0.50	28 SW T 523	P	
Lakeview Drive	1.10	28 T 524	P	Pothole near 914 needs patching. Subsidence near 1040 Lakeview needs fill, Rock?
Lyndhurst Bay Drive	1.00	21 T 400	P	Trees close to road 3-4 should be removed. Crack patch.
Magney Drive	1.40	21 T	P	Pothole Bob's drive and south. Crumbling blacktop west of Cary Road.
Maple Drive	1.10	33 T 439	P	Pothole just east of Cty 7, Alligator cracking East 50 ft. Should be part of County 7 Project

Perch Lake Township  
Road Inspection Tour April 25, 2022

Road	Miles	Section/ Road #	Paved/ Unpaved	Description of Work Needed or Road Conditions
Pine Grove Drive	0.40	33 NE T 522	P	Stripping 2021. A fair bit of alligator cracking next candidate for grind and re-pave
Reponen Road	3.60	25 T 329		Need arrow sign north curve.
Salmi Road	0.85	22/33 T 304	P	Needs fill on the shoulders both sides for most of the road. Crack patching
Simian Creek Drive	0.30	2/11 T 160		No change
Strand Road	2.10	27/34 T 132		Culvert #9 beaver activity
Town Road 535	1.50	7 T 535		No Change
Town Road 536	1.00	7/18 T 536		No change
Watkins Spur	0.35	28 NW T 525	P	Rebuild scheduled for this year
<b>TOTAL MILES</b>	22.23			
Supervisors Present				
<hr/> Keith Depre				
<hr/> Gary Harms				
<hr/> Steve Olson				